



## TIANJIN WUJIE LOGISTICS COMPANY

### PRE-SHIPMENT REPORT

Ref No :TJWU160323

Date of issue:2016-03-27

Description of Goods : Carbon SSAW steel pipe

Name & Address of Shipper :Changsha Hunan Steel Co.,LTD.

Port of loading: TIANJIN

Port of Discharge : MOMBASA PORT, KENYA

Country of Origin : P.R China.

Shipment method: Container ship

B/L No: /

#### **Pre-Shipment inspection in manufacturer place :**

- Quantity Checking: 843.2 M =180PCS
- Visual quality check random

During the Wujie Inspector arrived at factory, all the pipes had been finished manufacturing , the pipes body were given the Black painting ,all of sizes with beveled ends ,root face was found on the beveled ends, all pipes with submerged arc welded seam on external and internal surface of pipes ,all off pipes with marking on the body as above request ,no obvious defects of visual quality were found on site.

Marking : Please see the below photos

Remark : Each pipe with mark of "MADE IN CHINA" on the surface of pipe .

The Actual Findings as follow :

- Marking on the external surface of all pipes
- All of pipes with end protectors
- No rust and oxide skin on the surface of pipe
- Made In China was found on the external of pipes

**Result** : The visual quality check result was satisfied but the final result subject to the consignee's evaluation the details and pictures please refer the report below: